

## Coating of a BMW X-1


1. Mask off sensitive areas such as Plastic parts carefully.



2. Pre-Cleaning



**3. Remove swirl marks and micro scratches prior to application of the coating.**



**4. Application of the coating**





## 5. Buffing/Polishing the coating

