

DMCI

**Glass and Aluminum Cladding
Mockup**

MOCKUP :
Mockup Details :
Cleaning :
Coating :

DMCI
Cleaning and Protection of glass and aluminum cladding
Biosativa, Stainless Cleaner, Glass cleaners
Nanofied Specialized Coating for Glass and High Performance Coating

DMCI Building



DMCI is looking for solutions to prevent staining and corrossions on aluminum cladding and glass

MOCKUP	:	DMCI
Mockup Details	:	Cleaning and Protection of glass and aluminum cladding
Cleaning	:	Biosativa, Stainless Cleaner, Glass cleaners
Coating	:	Nanofied Specialized Coating for Glass and High Performance Coating


DMCI Building – Aluminum Cladding




DMCI Building aluminum cladding problems with staining and corrosions caused by acid rain, building runoff, oil, dirt, dust and other pollutants.

MOCKUP	:	DMCI
Mockup Details	:	Cleaning and Protection of glass and aluminum cladding
Cleaning	:	Biosativa, Stainless Cleaner, Glass cleaners
Coating	:	Nanofied Specialized Coating for Glass and High Performance Coating

DMCI Building – Aluminum Cladding (Cleaning and Application)



Dust and dirt is removed from aluminum cladding



Aluminum cladding coated with multipurpose coating provide invisible protection against corrosions

Aluminum cladding coated with High Performance coating restores original appearance of surface and provides massive protection against corrosions


Aluminum cladding coated with SI coating provide invisible protection against corrosions

MOCKUP	:	DMCI
Mockup Details	:	Cleaning and Protection of glass and aluminum cladding
Cleaning	:	Biosativa, Stainless Cleaner, Glass cleaners
Coating	:	Nanofied Specialized Coating for Glass and High Performance Coating

DMCI Building – Aluminum Cladding after 1 week and testing




Coated aluminum cladding remains clean and without corrosion after 1 week, water is sprayed on aluminum cladding notice that water beads and is being repelled by the coating



Water sprayed on uncoated area of the cladding is being repelled or not being allowed to roll off on coated aluminum cladding.

MOCKUP	:	DMCI
Mockup Details	:	Cleaning and Protection of glass and aluminum cladding
Cleaning	:	Biosativa, Stainless Cleaner, Glass cleaners
Coating	:	Nanofied Specialized Coating for Glass and High Performance Coating


DMCI Building – Aluminum Cladding after 1 week and testing



Oil / Grease applied on coated and uncoated aluminum cladding

MOCKUP	:	DMCI
Mockup Details	:	Cleaning and Protection of glass and aluminum cladding
Cleaning	:	Biosativa, Stainless Cleaner, Glass cleaners
Coating	:	Nanofied Specialized Coating for Glass and High Performance Coating


DMCI Building – Aluminum Cladding after 1 week and testing



Oil / Grease applied on coated and uncoated aluminum cladding. Images shows the Super Oleophobicity of the coated surface.

MOCKUP	:	DMCI
Mockup Details	:	Cleaning and Protection of glass and aluminum cladding
Cleaning	:	Biosativa, Stainless Cleaner, Glass cleaners
Coating	:	Nanofied Specialized Coating for Glass and High Performance Coating

DMCI Building – Glass windows



DMCI Building Glass window problems with glass staining, watermarks, scaling and corrosions caused by acid rain, building runoff, oil, dirt, dust and other pollutants.

MOCKUP	:	DMCI
Mockup Details	:	Cleaning and Protection of glass and aluminum cladding
Cleaning	:	Biosativa, Stainless Cleaner, Glass cleaners
Coating	:	Nanofied Specialized Coating for Glass and High Performance Coating

DMCI Building – Glass windows (Cleaning and Coating Application)



DMCI Building Glass window cleaned and protected with nanofied Specialized Coating for Glass

MOCKUP	:	DMCI
Mockup Details	:	Cleaning and Protection of glass and aluminum cladding
Cleaning	:	Biosativa, Stainless Cleaner, Glass cleaners
Coating	:	Nanofied Specialized Coating for Glass and High Performance Coating

DMCI Building – Glass windows (After 1 week)



BEFORE

Heavy glass corrosion on windows like watermarks, scaling, dust and dirt



After 1 week

Heavy glass corrosion is removed from glass window and remains clean and corrosion free