LANDEV

AMBASSADOR YUCHENGCO HOUSE RESTORATION AND PROTECTION Mockup

MOCKUP: LANDEV - Ambassador Yuchengco's house restoration and protection


MOCKUP DETAILS: LANDEV is looking for new solutions for stone, glass and wood protection

PROPOSED SOLUTION: nanofied High Performance Coating

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

STONE WALL RESTORATION AND PROTECTION



MOLDS, ALGAE, SCALING, STAINING AND DISCOLORATION ON STONE WALLS

Stone corrosions like molds, algae, scaling, and staining are result of moisture transmission through the stone that evaporates upon reaching the surface, leaving behind dissolved minerals and salts. Other causes of corrosions are UV Rays, acid rain, bird droppings, tree sap and pollution. Nanofied coatings helps prevent these kinds of stone corrosions by repelling the main causes of stone corrosions by protecting and sealing the stone.

LANDEV - Ambassador Yuchengco's house restoration and protection **MOCKUP**


LANDEV is looking for new solutions for stone, glass and wood protection **MOCKUP DETAILS**


PROPOSED SOLUTION: nanofied High Performance Coating

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

STONE WALL CLEANING AND COATING APPLICATION







Application of Nanofied High Performance Coating

STONE WALL CLEANING AND APPLICATION

Removing stone corrosions like watermarks and scaling is very time consuming, expensive, requires additional manpower and sometimes impossible to remove. Some stone corrosions requires special equipment and toxic chemicals to remove. Nanofied coatings helps prevent these kinds of stone corrosions by repelling the main causes of stone corrosions by protecting and sealing the stone.

MOCKUP: LANDEV - Ambassador Yuchengco's house restoration and protection

MOCKUP DETAILS : LANDEV is looking for new solutions for stone, glass and wood protection

PROPOSED SOLUTION: nanofied High Performance Coating

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

STONE WALL AFTER CLEANING AND COATING



After cleaning and coating, stone wall is noticeably brighter and cleaner. Nanofied High Performance Coating will provide extreme protection against molds, algae, scaling and staining.

Water is sprayed on coated stone wall. Water is being repelled by nanofied High Performance Coating.

MOCKUP DETAILS : LANDEV is looking for new solutions for stone, glass and wood restoration and

protection

PROPOSED SOLUTION: nanofied High Performance Coating

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

STONE WALL (Corner) RESTORATION AND PROTECTION



MOLDS, ALGAE, SCALING, STAINING AND DISCOLORATION ON STONE WALLS

Stone corrosions like molds, algae, scaling, and staining are result of moisture transmission through the stone that evaporates upon reaching the surface, leaving behind dissolved minerals and salts. Other causes of corrosions are UV Rays, acid rain, bird droppings, tree sap and pollution. Nanofied coatings helps prevent these kinds of stone corrosions by repelling the main causes of stone corrosions by protecting and sealing the stone.

MOCKUP DETAILS : LANDEV is looking for new solutions for stone, glass and wood restoration and


protection

PROPOSED SOLUTION: nanofied High Performance Coating

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

STONE WALL (Corners) CLEANING AND COATING APPLICATION



Staining and scaling is removed



Application of Nanofied High Performance Coating

STONE WALL CLEANING AND APPLICATION

Removing stone corrosions like watermarks and scaling is very time consuming, expensive, requires additional manpower and sometimes impossible to remove. Some stone corrosions requires special equipment and toxic chemicals to remove. Nanofied coatings helps prevent these kinds of stone corrosions by repelling the main causes of stone corrosions by protecting and sealing the stone.

MOCKUP DETAILS: LANDEV is looking for new solutions for stone, glass and wood restoration and


protection

PROPOSED SOLUTION: nanofied High Performance Coating

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

STONE WALL (Corner) AFTER CLEANING AND COATING



After cleaning and coating, stone wall is noticeably brighter and cleaner. Nanofied High Performance Coating will provide extreme protection against molds, algae, scaling and staining.

MOCKUP DETAILS : LANDEV is looking for new solutions for stone, glass and wood restoration and

protection

PROPOSED SOLUTION: nanofied High Performance Coating

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

SANDSTONE FLOORING RESTORATION AND PROTECTION



STAINING ON SAND STONE FLOORING (POOL AREA)

Sandstone staining are from bird droppings and tree sap. Scaling, molds, and algae are from moisture transmission through the sandstone that evaporates upon reaching the surface, leaving behind dissolved minerals and salts. Nanofied coatings helps prevent these kinds of stone corrosions by repelling the main causes of stone corrosions by protecting and sealing the stone.

LANDEV MOCKUP

LANDEV is looking for new solutions for stone, glass and wood restoration and **MOCKUP DETAILS**

protection

nanofied High Performance Coating **PROPOSED SOLUTION:**

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

SAND STONE (Pool Area) CLEANING AND COATING APPLICATION





Application of Nanofied Specialized Coating for Stone

SANDSTONE FLOORING (POOL AREA) CLEANING AND APPLICATION

Removing stone corrosions like watermarks and scaling is very time consuming, expensive, requires additional manpower and sometimes impossible to remove. Some stone corrosions requires special equipment and toxic chemicals to remove. Nanofied coatings helps prevent these kinds of stone corrosions by repelling the main causes of stone corrosions by protecting and sealing the stone.

MOCKUP DETAILS: LANDEV is looking for new solutions for stone, glass and wood restoration and

protection

PROPOSED SOLUTION: nanofied High Performance Coating

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

STONE FLOORING (Lanai) RESTORATION AND PROTECTION





MOLDS, ALGAE, SCALING, STAINING AND DISCOLORATION ON STONE FLOORING (LANAI AREA)

Stone corrosions like molds, algae, scaling, and staining are result of moisture transmission through the stone that evaporates upon reaching the surface, leaving behind dissolved minerals and salts. Other causes of corrosions are UV Rays, acid rain, bird droppings, tree sap and pollution. Nanofied coatings helps prevent these kinds of stone corrosions by repelling the main causes of stone corrosions by protecting and sealing the stone.

MOCKUP DETAILS: LANDEV is looking for new solutions for stone, glass and wood restoration and

protection

PROPOSED SOLUTION: nanofied High Performance Coating


nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

STONE FLOORING (Lanai) CLEANING AND COATING APPLICATION



Staining and scaling is removed



Application of Nanofied High Performance Coating

STONE FLOORING (LANAI AREA) CLEANING AND APPLICATION

Removing stone corrosions like watermarks and scaling is very time consuming, expensive, requires additional manpower and sometimes impossible to remove. Some stone corrosions requires special equipment and toxic chemicals to remove. Nanofied coatings helps prevent these kinds of stone corrosions by repelling the main causes of stone corrosions by protecting and sealing the stone.

MOCKUP: LANDEV - Ambassador Yuchengco's house restoration and protection


MOCKUP DETAILS: LANDEV is looking for new solutions for stone, glass and wood protection

PROPOSED SOLUTION: nanofied High Performance Coating

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

STONE FLOORING (Lanai) AFTER CLEANING AND COATING



MOCKUP DETAILS: LANDEV is looking for new solutions for stone, glass and wood restoration and

protection

PROPOSED SOLUTION: nanofied High Performance Coating

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

HOUSE RESTORATION AND SURFACE PROTECTION



HEAVY SCALING AND WATERMARKS ON GLASS ROOFING

Glass corrosions like watermarks and scaling are caused by calcium left behind by water after it evaporates. These watermarks and scaling when not given proper attention will be very difficult to remove or sometimes may cause damage to glass. Other causes of glass corrosions are: acid rain, bird droppings, tree saps and pollution. Removing watermarks and scaling is very time consuming, expensive and sometimes impossible. Nanofied coatings helps prevent these kinds of glass corrosions by protecting and sealing the glass by repelling the main causes of glass corrosions.

MOCKUP DETAILS : LANDEV is looking for new solutions for stone, glass and wood restoration and

protection

PROPOSED SOLUTION: nanofied High Performance Coating

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

WOOD PANEL RESTORATION AND PROTECTION



WOOD PANEL RESTORATION AND PROTECTION

Nanofied coatings helps preserve wooden structures by protecting and sealing the wood against moisture and other environmental hazards.

MOCKUP DETAILS: LANDEV is looking for new solutions for stone, glass and wood restoration and


protection

PROPOSED SOLUTION: nanofied High Performance Coating

nanofied Specialized Coating for Stone and Wood

nanofied Specialized Coating for Glass

WOOD PANEL RESTORATION AND PROTECTION (After Coating)



WOODEN PANEL RESTORATION AND PROTECTION

Nanofied coatings helps preserve wooden structures by protecting and sealing the wood against moisture and other environmental hazards.